



FTW04

Standard labelling (only with option potentiometer)

FTW04 P standard labelling
(ltypeS)



FTW04 P standard labelling colour
(refer to options – ltypeSC)



Item description: product | VV / AA

Room sensor humidity + temperature – active 2x 0..10 V 2x 4..20 mA			HU2
Item description	Item No.	On stock	
FTW04 VV	196352	●	
FTW04 AA	609555	●	

Options
Item description
LCD (only type VV VVS)
Potentiometer (passive)
Default labelling P colour red+blue (ltypeSC)
Additional passive temperature sensor

Order example for different items:

FTW04 | P | VV | PT1000 | LCD

- FTW04 = product
- P = potentiometer (10 kOhm)
- VV = 2x 0..10 V output
- PT1000 = additional passive temperature sensor
- LCD = display

FTW04 BUS

Item description: product | BUS



Room sensor humidity + temperature – active BUS			HU2
Item description	Item No.	On stock	
FTW04 RS485 Modbus	601153	☺	
FTW04 RS485 BACnet (MS/TP)	548298		



Room sensor humidity + temperature – active BUS			HU1
Item description	Item No.		
FTW04 KNX	585606		
FTW04 LON	297776		

Options	
Item description	
LCD (available for LON and RS485 Modbus)	
Potentiometer (passive; available for LON and RS485 Modbus)	
Default labelling P colour red+blue (ltypeSC)	

Order example for different items:

FTW04 | P | LON | LCD | standard labelling colour

FTW04 = product
P = potentiometer (10 kOhm)
LON = BUS
LCD = display
Labelling = standard red-blue

Accessories			AS1
Item description	Item No.	On stock	
Rawlplugs and screws (2 pcs. each)	102209	☺	
PSU-UP24 – flush mount power supply 24 V (80..240 V ~ -> 24 V =, 0,5 A)	645737	☺	
Frame for surface mounting NOVOS 3/WRF04	111584	☺	
Ball stroke protection BS150, transparent (for series WRF04)	647007	☺	